

Our Ref.: G1B218596/17/AG4/EMO/RMP

Date: 21st May 2020

NUNEATON & BEDWORTH BOROUGH COUNCIL
Cheverel Place
Nuneaton
Warwickshire
CV11 5SF

For the attention of Hazel Wilson

Inspection Details

Type : Policy
Number : G1B218596-17 Report Nos. : 001-002
Class : Lifting & Handling Plant
Surveyor : Mr A Gernon
Date : 20th May 2020
Location : As attached

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the method statements documented in Section 13.5 of the Company Quality Procedures.

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.

Risk Solutions

HSB Engineering Insurance Services Limited
Chancery Place, 50 Brown Street,
Manchester M2 2JT
Telephone: 0845 345 5510
Fax: 0845 345 5610
Web: www.hsbeil.com

Registered in England and Wales: 03010292
Registered office: New London House,
6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105



HSB Engineering Insurance

REPORT OF DELETED ITEMS

Policy: G1B0218596

Previous Report: 021219-001-0002EMO

Site : 00017

Report Number : 210520-001-0003EMO

DEL11

Occupier NUNEATON & BEDWORTH BOROUGH COUNCIL

Address Cheverel Place, Nuneaton,
Warwickshire, CV11 5SF


Sched No.	Plant Code	Item	Remarks
L0002	L24AHH	Passenger/Goods Lift Electric Serving 2 Floors S.No.:NU010 Wadsworth Becker SWL: 13 persons/975kg	Object has been deleted from site plant schedule. Due to an administrative error this was a duplicated object. Name of person who confirmed deletion Anthony Gernon

I/we hereby advise that the above items of equipment have been deleted from the plant schedule with effect from the date(s) shown.

Date 20 May 2020

Inspecting Engineer: Mr A Gernon

Signature:



Qualification: Engineer Surveyor

REPORT OF PERIODIC THOROUGH EXAMINATION OF HOIST OR LIFT

as required by the Lifting Operation and Lifting Equipment Regulations 1998;
or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999;
or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: G1B0218596

Plant Code: L27AHH

Previous Report:

Site: 00017

Schedule: L0003

Report Number: 210520-002-0003EMO

L0L54

Employer (or owner) of premises	NUNEATON & BEDWORTH BOROUGH COUNCIL	
Address	Cheverel Place, Nuneaton, Warwickshire, CV11 5SF	
1. (a) Type of hoist or lift and identification number and description	Passenger/Goods Lift	Hydraulic
(b) Date of construction or reconstruction (if ascertainable)	Serving 2 floors Wadsworth Becker Serial No.:- NU010 Unknown	
2. (a) Is this the first thorough examination following installation of the equipment at the above site/location?	No	
(b) Were examinations in accordance with an examination scheme?	No	
3. Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use.		
(a) Enclosure of hoistway or liftway.	Yes	
(b) Landing gates and cage gate(s).	Yes	
(c) Interlocks on the landing gates and cage gate(s).	Yes	
(d) Other gate fastenings.	Yes	
(e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.	Yes	
(f) Over-running devices.	Yes	
(g) Suspension ropes or chains, and their attachments.	Yes	
(h) Safety gear, i.e. arrangements for preventing fall of platform or cage.	Yes	
(j) Brakes.	Yes	
(k) Worm or spur gearing.	Not applicable.	
(l) Other electrical equipment.	Yes	
(m) Other parts.	Yes	
4. What parts (if any) were inaccessible?	Enclosed electrical, mechanical and structural components	
5. Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None") :-		
(a) defects found which give rise to imminent danger and require attention immediately.	None	
(b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period.	None	
6. Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.	13 Person/	
7. Other observations	Last serviced - 01/05/2020	

This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.


Date of Examination: 20 May 2020

Date of Last Examination: ---

Inspecting Engineer: Mr A Gernon

Date of Next Examination: 20 Nov 2020

Signature:



Qualification: Engineer Surveyor