



<b>Equip No:</b>		<b>Inspect No:</b>	54387
<b>Make/Model:</b>		<b>Job No:</b>	42637
<b>Serial No:</b>		<b>Contact:</b>	Tom Saunders
<b>Cust Equip No:</b>		<b>Inspected:</b>	02/07/2020
<b>Meter:</b>		<b>Printed:</b>	29/07/2020

<b>Site:</b>	Nuneaton & Bedworth Borough Council - Poplar House Poplar House Poplar Avenue BEDWORTH CV12 9ER
--------------	---

Items to Inspect	Result	Comments
<b>General</b>		
EL service contract in place	Yes	
FA service contract in place	Yes	
FFE service contract in place	N/A	No FFE on site
Fire wardens trained on site	N/A	No FFE on site
Have you confirmed the absence of Asbestos prior to commencing works	Yes	
FRA completed/reviewed in the last 12 months	Yes	
Site log book completed	No NR	Log book not signed

Service carried out by: Engineer Name: Jonathan Lander  
 Signature:

Customer Name: Ron  
 Signature:



## BS5306-8:2017 FFE Commissioning Certificate

<b>Equip No:</b>		<b>Inspect No:</b>	54388
<b>Make/Model:</b>		<b>Job No:</b>	42637
<b>Serial No:</b>		<b>Contact:</b>	Tom Saunders
<b>Cust Equip No:</b>		<b>Inspected:</b>	02/07/2020
<b>Meter:</b>		<b>Printed:</b>	29/07/2020

<b>Site:</b>	Nuneaton & Bedworth Borough Council - Poplar House Poplar House Poplar Avenue BEDWORTH CV12 9ER
--------------	---

Items to Inspect	Result	Comments
<b>General FFE</b>		
All new equipment has been installed & commissioned in accordance with BS5306-8:2017	Yes	
Extent of the site covered by this certificate	N/A	
Site has outstanding work required to comply with BS5306-8:2017	No	

Service carried out by: Engineer Name: Jonathan Lander  
 Signature:

Customer Name: Ron  
 Signature: