



Emergency Light Maintenance Attendance Certificate

System serviced in accordance with BS5266-1

Site name & address Nuneaton + Bedworth Borough Council Reg Haddon Court Shanklin Drive Nuneaton Post code CV10 0DD Contact name John Sweeney Telephone 024 7637 6464 Site Mobile 07769 881759 Site e-mail Contract number MD-M58670	Call type Routine Maintenance Visit date 14/10/2020 Job number 1256668 Appointment booked by Claire Long System type Emergency Lighting Panel type light Panel location/number Customer Order Number Contract extension 4 Engineer David Walker
--	---

Site	Luminaires located at the following positions																
All relevant information and documentation available <input checked="" type="checkbox"/> Inform customer system on test <input checked="" type="checkbox"/> Check log book for previous faults <input checked="" type="checkbox"/>	At each emergency exit door <input checked="" type="checkbox"/> Within 2m of stair treads/level change <input checked="" type="checkbox"/> Within 2m of exit and safety signs <input checked="" type="checkbox"/> At intersection of corridors <input type="checkbox"/> NA At each change of direction <input checked="" type="checkbox"/> Outside and within 2m of final exits <input checked="" type="checkbox"/> Within 2m of each first aid point <input type="checkbox"/> NA Within 2m fire fighting equipment and call points <input type="checkbox"/> NA																
Luminaires	Additional luminaires located at the following positions																
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%;">Main manufacturer/model</td> <td style="text-align: right;">bulkhead</td> </tr> <tr> <td>Number of non-maintained luminaires</td> <td style="text-align: right;">21</td> </tr> <tr> <td>Number of non-maintained luminaires, maintained signs</td> <td style="text-align: right;">0</td> </tr> <tr> <td>Number of maintained luminaires</td> <td style="text-align: right;">0</td> </tr> <tr> <td>Number of slaves</td> <td style="text-align: right;">0</td> </tr> <tr> <td>Duration of system tested</td> <td style="text-align: right;">3 hour</td> </tr> <tr> <td>Total number tested</td> <td style="text-align: right;">21</td> </tr> <tr> <td>No. of luminaires failed</td> <td style="text-align: right;">1</td> </tr> </table>	Main manufacturer/model	bulkhead	Number of non-maintained luminaires	21	Number of non-maintained luminaires, maintained signs	0	Number of maintained luminaires	0	Number of slaves	0	Duration of system tested	3 hour	Total number tested	21	No. of luminaires failed	1	Lift cars <input type="checkbox"/> NA Moving Stairways and walkways <input type="checkbox"/> NA Disabled Toilets <input type="checkbox"/> NA Motor generator room, control & plant rooms <input type="checkbox"/> NA Covered car parks <input type="checkbox"/> NA
Main manufacturer/model	bulkhead																
Number of non-maintained luminaires	21																
Number of non-maintained luminaires, maintained signs	0																
Number of maintained luminaires	0																
Number of slaves	0																
Duration of system tested	3 hour																
Total number tested	21																
No. of luminaires failed	1																

System status
Have you returned the system to its normal operational state to the best of your knowledge Yes If not why?

Works completed/engineer findings
A/ Routine service of emergency lighting.3 hours discharge test B/ Below is a list of all failures outside flat 5 C/ All lighting put back to normal D/ Not all lights are barcoded

Works to be completed
none

Customer actions & recommendations
none

Equipment required
Qty Item Description
1 EMLED3M - Emergency Light LED BULKHEAD Maintained/Non Maintained 3Hr IP65

Timesheet							
Engineer	Call Date	Travel	Time On Site	Time Off Site	Arrive Back	Total Hours	Engineers Notes
David Walker	14/10/2020	07:29	08:14	11:33		4.07	

Customer signature



Engineer signature



Customer Position none

Engineer Name David Walker

Reason for no signature if applicable: Not Presen