

Our Ref.: G1B218596/36/AG4/EMO/RMP

Date: 4th February 2021

**NUNEATON & BEDWORTH BOROUGH COUNCIL**  
**Springdale Court**  
**Nuneaton**  
**Warwickshire**  
**CV11 4TU**

**For the attention of Melanie Salt**

Inspection Details

Type : Policy  
Number : G1B218596-36 Report Nos. : 001-001  
Class : Lifting & Handling Plant  
Surveyor : Mr A Gernon  
Date : 3rd February 2021  
Location : As attached

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the method statements documented in Section 13.5 of the Company Quality Procedures.

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.

# REPORT OF PERIODIC THOROUGH EXAMINATION OF HOIST OR LIFT

as required by the Lifting Operation and Lifting Equipment Regulations 1998;  
or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999;  
or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: G1B0218596

Plant Code: L27AHH

Previous Report: 010720-002-0003EMO

Site: 00036

Schedule: L0002

Report Number: 040221-001-0004EMO

L0L54

|   |   |           |
|---|---|-----------|
| Employer (or owner) of premises   | NUNEATON & BEDWORTH BOROUGH COUNCIL                       |           |
| Address   | Springdale Court, Nuneaton,<br>Warwickshire, CV11 4TU     |           |
| 1. (a) Type of hoist or lift and identification number and description  | Passenger/Goods Lift                                      | Hydraulic |
| (b) Date of construction or reconstruction (if ascertainable)   | Axis Elevators<br>Serial No.:- 21206<br>Unknown           |           |
| 2. (a) Is this the first thorough examination following installation of the equipment at the above site/location?   | No  |           |
| (b) Were examinations in accordance with an examination scheme?   | No  |           |
| 3. Maintenance<br>Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use. |   |           |
| (a) Enclosure of hoistway or liftway.   | Yes   |           |
| (b) Landing gates and cage gate(s).   | Yes   |           |
| (c) Interlocks on the landing gates and cage gate(s).   | Yes   |           |
| (d) Other gate fastenings.  | Yes   |           |
| (e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.   | Yes   |           |
| (f) Over-running devices.   | Yes   |           |
| (g) Suspension ropes or chains, and their attachments.  | Yes   |           |
| (h) Safety gear, i.e. arrangements for preventing fall of platform or cage.   | Yes   |           |
| (j) Brakes.   | Not applicable.   |           |
| (k) Worm or spur gearing.   | Not applicable.   |           |
| (l) Other electrical equipment.   | Yes   |           |
| (m) Other parts.  | Yes   |           |
| 4. What parts (if any) were inaccessible?   | Enclosed electrical, mechanical and structural components |           |
| 5. Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None") :-  |   |           |
| (a) defects found which give rise to imminent danger and require attention immediately.   | None  |           |
| (b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period.   | None  |           |
| 6. Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.   | 1100kg/14 Persons   |           |
| 7. Other observations   | None  |           |

This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.


Date of Examination: 03 Feb 2021

Date of Last Examination: 30 Jun 2020

Inspecting Engineer: Mr A Gernon

Date of Next Examination: 03 Aug 2021

Signature:



Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292,  
New London House, 6 London Street, London EC3R 7LP  
Registered as a branch in Ireland: 906105  
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited  
is accredited by the United Kingdom  
Accreditation Service



010