

Our Ref.: G1B218596/38/SC3/EMO/RMP

Date: 14th July 2021

NUNEATON & BEDWORTH BOROUGH COUNCIL
The Chines
Ryde Avenue
Nuneaton
Warwickshire
CV10 0BH

For the attention of Mr Bradbury / Miss Keegans

Inspection Details

Type : Policy
Number : G1B218596-38 Report Nos. : 001-001
Class : Lifting & Handling Plant
Surveyor : Mr S Callaghan
Date : 13th July 2021
Location : As attached

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the method statements documented in Section 13.5 of the Company Quality Procedures.

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.

**REPORT OF PERIODIC THOROUGH EXAMINATION
OF HOIST OR LIFT**

as required by the Lifting Operation and Lifting Equipment Regulations 1998;
or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999;
or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: G1B0218596

Plant Code: L27AHH

Previous Report: 190121-001-0005EMO

Site: 00038

Schedule: L0002

Report Number: 140721-001-0006EMO

L0L54

Employer (or owner) of premises	NUNEATON & BEDWORTH BOROUGH COUNCIL	
Address	The Chines, Ryde Avenue, Nuneaton, Warwickshire CV10 0BH	
1. (a) Type of hoist or lift and identification number and description	Passenger/Goods Lift	Hydraulic
(b) Date of construction or reconstruction (if ascertainable)	Fussi Serial No.:- 3959 Unknown	
2. (a) Is this the first thorough examination following installation of the equipment at the above site/location?	No	
(b) Were examinations in accordance with an examination scheme?	No	
3. Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use.		
(a) Enclosure of hoistway or liftway.	Yes	
(b) Landing gates and cage gate(s).	Yes	
(c) Interlocks on the landing gates and cage gate(s).	Yes	
(d) Other gate fastenings.	Yes	
(e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.	Yes	
(f) Over-running devices.	Yes	
(g) Suspension ropes or chains, and their attachments.	Not applicable, direct acting cylinder.	
(h) Safety gear, i.e. arrangements for preventing fall of platform or cage.	Yes	
(j) Brakes.	Not applicable.	
(k) Worm or spur gearing.	Not applicable.	
(l) Other electrical equipment.	Yes	
(m) Other parts.	Yes	
4. What parts (if any) were inaccessible?	Enclosed electrical, mechanical and structural components	
5. Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None") :-		
(a) defects found which give rise to imminent danger and require attention immediately.	None	
(b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period.	None	
6. Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.	1000 kg/13 persons	
7. Other observations	See Plant Report Continuation	

This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.

Date of Examination: 13 Jul 2021

Date of Last Examination: 25 Jun 2020

Inspecting Engineer: Mr S Callaghan

Date of Next Examination: 13 Jan 2022

Signature:



Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292,
New London House, 6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited
is accredited by the United Kingdom
Accreditation Service



PLANT REPORT CONTINUATION



Policy: G1B0218596

Plant Code: L27AHH

Previous Report: 190121-001-0005EMO

Site : 00038

Schedule: L0002

Report Number : 140721-001-0006EMO

Occupier NUNEATON & BEDWORTH BOROUGH COUNCIL

Address The Chines, Ryde Avenue,
Nuneaton, Warwickshire
CV10 0BH

PRC1

Section	Remarks
7	Last serviced:05/07/21 Supplementary test carried out on 17/03/21, please leave a copy of test certificate with log book for engineer to view.

Date of Examination: 13 Jul 2021

Date of Last Examination: 25 Jun 2020

Inspecting Engineer: Mr S Callaghan

Date of Next Examination: 13 Jan 2022

Signature: 

Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292,
New London House, 6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited
is accredited by the United Kingdom
Accreditation Service

