

Our Ref.: G1B218596/12/AG4/EMO/RMP

Date: 23rd June 2020

NUNEATON & BEDWORTH BOROUGH COUNCIL
Arthur Alford House
Bedworth
Warwickshire
CV12 0JT

For the attention of Arlene Hayden

Inspection Details

Type : Policy
Number : G1B218596-12 Report Nos. : 001-001
Class : Lifting & Handling Plant
Surveyor : Mr A Gernon
Date : 22nd June 2020
Location : As attached

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

The attached documentation contains reports on some items of plant and machinery which were not subject to inspection to any particular Regulation. The items concerned are identified and the responsibility for compliance with any regulations deemed applicable by Regulatory Authorities or any other party, in their operation and usage, rests with the owner/user. If you wish any such equipment inspected in accordance with a specific criteria, this must be detailed in the Policy/Contract prior to the inspection taking place.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the inspection methods and procedures as documented in Section 7.1 of the Company Quality Assurance Policy (Manual).

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.

Risk Solutions

HSB Engineering Insurance Services Limited
Chancery Place, 50 Brown Street,
Manchester M2 2JT
Telephone: 0845 345 5510
Fax: 0845 345 5610
Web: www.hsbeil.com

Registered in England and Wales: 03010292
Registered office: New London House,
6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105



HSB Engineering Insurance

PLANT INSPECTION REPORT

Policy: G1B0218596

Previous Report: 100719-001-0001CG3

Site : 00012

Report Number : 230620-001-0002EMO

PIR1

Occupier NUNEATON & BEDWORTH BOROUGH COUNCIL

Address Arthur Alford House, Bedworth,
Warwickshire, CV12 0JT

Sched No.	Plant Code	Item	Remarks
L0001	L30A10	Stair Lift S.No.:MO2132388 SWL: 115 kg/1 Person Locn.:On Site	Remote control not working advise attention.

This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).


Date of Inspection: 22 Jun 2020

Date of Last Inspection: 03 Jul 2019

Inspecting Engineer: Mr A Gernon

Date of Next Inspection: 22 Jun 2021

Signature:



Qualification: Engineer Surveyor