

# PLANT INSPECTION REPORT

Policy: G1B0218596

Previous Report: 040919-001-0001TE1

Site : 00023

Report Number : 100920-001-0002EMO

PIR1

Occupier NUNEATON & BEDWORTH BOROUGH COUNCIL

Address James Diskin Court, Nuneaton,  
Warwickshire, CV11 4QA

| Sched No. | Plant Code | Item   | Remarks  |
|-----------|------------|--|--|
| L0001     | L30A10     | Stair Lift<br>S.No.:M10142046<br>SWL: 1Person/115kg<br>Locn.:On Site   | No apparent defects.<br>Last serviced 16/7/2020  |
| L0002     | L30A10     | Stair Lift<br>S.No.:NOT MARKRED<br>SWL: 1Person/115kg<br>Locn.:On Site | Clearly mark with unique serial number.<br>Fit missing screw at top gear bracket.<br>Last serviced 16/7/2020 |

This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).


Date of Inspection: 09 Sep 2020

Date of Last Inspection: 02 Sep 2019

Inspecting Engineer: Mr A Gernon

Date of Next Inspection: 09 Sep 2021

Signature:



Qualification: Engineer Surveyor