



Equip No:		Inspect No:	55566
Make/Model:		Job No:	43734
Serial No:		Contact:	Tom Saunders
Cust Equip No:		Inspected:	08/06/2020
Meter:		Printed:	28/07/2020

Site:	Nuneaton & Bedworth Borough Council - Leonard Perkins House Elm Tree Road BULKINGTON CV12 9RL
--------------	--

Items to Inspect	Result	Comments
General		
EL service contract in place	Yes	
FA service contract in place	Yes	
FFE service contract in place	N/A	No FFE on site
Fire wardens trained on site	N/A	No FFE on site
Have you confirmed the absence of Asbestos prior to commencing works	Yes	
FRA completed/reviewed in the last 12 months	Yes	
Site log book completed	No NR	Log book not signed

Service carried out by: Engineer Name: Jonathan Lander
 Signature:

Customer Name: Nikki
 Signature:



BS5306-8:2017 FFE Commissioning Certificate

Equip No:		Inspect No:	55567
Make/Model:		Job No:	43734
Serial No:		Contact:	Tom Saunders
Cust Equip No:		Inspected:	08/06/2020
Meter:		Printed:	28/07/2020

Site:	Nuneaton & Bedworth Borough Council - Leonard Perkins House Elm Tree Road BULKINGTON CV12 9RL
--------------	--

Items to Inspect	Result	Comments
General FFE		
All new equipment has been installed & commissioned in accordance with BS5306-8:2017	Yes	
Extent of the site covered by this certificate	N/A	
Site has outstanding work required to comply with BS5306-8:2017	No	

Service carried out by: Engineer Name: Jonathan Lander
 Signature:

Customer Name: Nikki
 Signature: