

Our Ref.: G1B218596/43/SC3/EMO/RMP

Date: 9th October 2020

NUNEATON & BEDWORTH BOROUGH COUNCIL
Alwynne Freeman Court
Somers Road
Nuneaton
Warwickshire
CV7 8NW

For the attention of Eileen O'Shea

Inspection Details

Type : Policy
Number : G1B218596-43 Report Nos. : 001-001
Class : Lifting & Handling Plant
Surveyor : Mr S Callaghan
Date : 8th October 2020
Location : As attached

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

The attached documentation contains reports on some items of plant and machinery which were not subject to inspection to any particular Regulation. The items concerned are identified and the responsibility for compliance with any regulations deemed applicable by Regulatory Authorities or any other party, in their operation and usage, rests with the owner/user. If you wish any such equipment inspected in accordance with a specific criteria, this must be detailed in the Policy/Contract prior to the inspection taking place.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the inspection methods and procedures as documented in Section 7.1 of the Company Quality Assurance Policy (Manual).

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.

PLANT INSPECTION REPORT



Policy: G1B0218596

Previous Report: 231019-001-0001EMO

Site : 00043

Report Number : 091020-001-0002EMO

PIR1

Occupier NUNEATON & BEDWORTH BOROUGH COUNCIL

Address Alwynne Freeman Court, Somers Road,
Nuneaton, Warwickshire
CV7 8NW

Sched No.	Plant Code	Item	Remarks
L0001	L30A10	Stair Lift Stannah SWL: 120 Kg Locn.:On Site	Clearly mark with unique serial number. Advise service log card is kept on site. Safety gear to be tested in accordance with manufacturers recommendations. Ensure item is serviced and maintained in accordance with manufactures recommendations.

This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).

Date of Inspection: 08 Oct 2020

Date of Last Inspection: 22 Oct 2019

Inspecting Engineer: Mr S Callaghan

Date of Next Inspection: 08 Oct 2021

Signature:

Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292,
New London House, 6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited
is accredited by the United Kingdom
Accreditation Service

