

# PLANT INSPECTION REPORT



**Policy:** G1B0218596

**Previous Report:** 231019-001-0001EMO

**Site :** 00024

**Report Number :** 161020-001-0002EMO

**PIR1**

**Occupier** NUNEATON & BEDWORTH BOROUGH COUNCIL

**Address** John Hayes Court, Exhall,  
Warwickshire, CV7 9GG

| Sched No. | Plant Code | Item   | Remarks  |
|-----------|------------|--|--|
| L0001     | L30A10     | Stair Lift<br>S.No.:1102012664000<br>Acorn<br>SWL: 127 Kg<br>Locn.:On Site | No apparent defects.<br>Advise service log card is kept on site.<br>Safety gear to be tested in accordance with manufacturers recommendations. |

**This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).**

**Date of Inspection:** 08 Oct 2020

**Date of Last Inspection:** 22 Oct 2019

**Inspecting Engineer:** Mr S Callaghan

**Date of Next Inspection:** 08 Oct 2021

**Signature:**

**Qualification:** Engineer Surveyor

## HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292,  
New London House, 6 London Street, London EC3R 7LP  
Registered as a branch in Ireland: 906105  
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited  
is accredited by the United Kingdom  
Accreditation Service

