

PLANT INSPECTION REPORT

Policy: G1B0218596

Previous Report: 130719-001-0001JK

Site : 00044

Report Number : 010720-001-0002EMO

PIR1

Occupier NUNEATON & BEDWORTH BOROUGH COUNCIL

Address Leonard Perkins House, Elm Tree Road,
Bulkington, Warwickshire
CV12 9RL

Sched No.	Plant Code	Item	Remarks
L0001	L30A10	Stair Lift S.No.:M02152255 Handicare SWL: 115 kg Locn.:On Site	No apparent defects
L0002	L30A10	Stair Lift S.No.:M12152139 Handicare SWL: 115 kg Locn.:On Site	No apparent defects

This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).


Date of Inspection: 29 Jun 2020

Date of Last Inspection: 05 Jul 2019

Inspecting Engineer: Mr A Gernon

Date of Next Inspection: 29 Jun 2021

Signature:



Qualification: Engineer Surveyor