

PLANT INSPECTION REPORT

Policy: G1B0218596

Previous Report: 040919-001-0001TE1

Site : 00034

Report Number : 100920-001-0002EMO

PIR1

Occupier NUNEATON & BEDWORTH BOROUGH COUNCIL

Address Priory Court, Nuneaton,
Warwickshire, CV11 5HW

| Sched No. | Plant Code | Item | Remarks |
|-----------|------------|---|---|
| L0001 | L30A10 | Stair Lift S.No.:G0358090 SWL: 120kg/1 Person Locn.:On Site | Year of manufacture: 2004 Advise service log card is kept on site. |
| L0002 | L30A10 | Stair Lift S.No.:U2600404127 SWL: 120kg/1 Person Locn.:On Site | Year of manufacture: 2004 Advise service log card is kept on site. |

This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).


Date of Inspection: 09 Sep 2020

Date of Last Inspection: 03 Sep 2019

Inspecting Engineer: Mr A Gernon

Date of Next Inspection: 09 Sep 2021

Signature:



Qualification: Engineer Surveyor