



Emergency Light Maintenance Attendance Certificate

System serviced in accordance with BS5266-1

Site name & address Nuneaton + Bedworth Borough Council Leonard Perkins House Elm Tree Road Bedworth Post code CV12 9RL Contact name John Sweeney Telephone 024 7637 6464 Site Mobile Site e-mail Contract number MD-M58688	Call type Routine Maintenance Visit date 26/10/2020 Job number 1256654 Appointment booked by Claire Long System type Emergency Lighting Panel type notifier id2000 Panel location/number Customer Order Number Contract extension 4 Engineer Andrew Martin
--	---

Site	Luminaires located at the following positions
All relevant information and documentation available <input checked="" type="checkbox"/> Inform customer system on test NA Check log book for previous faults <input checked="" type="checkbox"/>	At each emergency exit door NA Within 2m of stair treads/level change NA Within 2m of exit and safety signs NA At intersection of corridors NA At each change of direction NA Outside and within 2m of final exits NA Within 2m of each first aid point NA Within 2m fire fighting equipment and call points NA
Luminaires	Additional luminaires located at the following positions
Main manufacturer/model spotlights Number of non-maintained luminaires 42 Number of non-maintained luminaires, maintained signs Number of maintained luminaires Number of slaves Duration of system tested 3 hour Total number tested 42 No. of luminaires failed	Lift cars NA Moving Stairways and walkways NA Disabled Toilets NA Motor generator room, control & plant rooms NA Covered car parks NA

System status
Have you returned the system to its normal operational state to the best of your knowledge If not why?

Works completed/engineer findings
3 hour emergency light test completed all areas tested no issues logbooks completed new emergency lighting system been installed need to barcode devices and add onto zeta please allow labour time

Works to be completed

Customer actions & recommendations

Timesheet	Call Date	Travel	Time On Site	Time Off Site	Arrive Back	Total Hours	Engineers Notes
Engineer Andrew Martin	26/10/2020	09:00	10:16	13:15		4.25	

Customer signature

Engineer signature



Customer Position

Engineer Name

Andrew Martin

Reason for no signature if applicable: Not Present