

Emergency Light Maintenance Attendance Certificate

System serviced in accordance with BS5266-1

Site name & address Nuneaton + Bedworth Borough Council Priory Court Countess Road Nuneaton Post code CV11 5HW Contact name John Sweeney Telephone 024 7637 6464 Site Mobile 07748931086 Site e-mail Contract number MD-M58669	Call type Routine Maintenance Visit date 21/09/2020 Job number 1255579 Appointment booked by Claire Long System type Emergency Lighting Panel type Notifier ID2K Panel location/number Customer Order Number Contract extension 4 Engineer Andrew Martin
---	--

Site	Luminaires located at the following positions
All relevant information and documentation available <input checked="" type="checkbox"/>	At each emergency exit door NA
Inform customer system on test NA	Within 2m of stair treads/level change NA
Check log book for previous faults <input checked="" type="checkbox"/>	Within 2m of exit and safety signs NA
	At intersection of corridors NA
	At each change of direction NA
	Outside and within 2m of final exits NA
	Within 2m of each first aid point NA
	Within 2m fire fighting equipment and call points NA
Luminaires	Additional luminaires located at the following positions
Main manufacturer/model 8w bulkheads	Lift cars NA
Number of non-maintained luminaires 33	Moving Stairways and walkways NA
Number of non-maintained luminaires, maintained signs	Disabled Toilets NA
Number of maintained luminaires	Motor generator room, control & plant rooms NA
Number of slaves	Covered car parks NA
Duration of system tested 3 hour	
Total number tested 33	
No. of luminaires failed 1	

System status
Have you returned the system to its normal operational state to the best of your knowledge Yes If not why?

Works completed/engineer findings
3 hour emergency light test completed all areas tested 1 x 8w fire sign eml fitting failed adj office in corridor above doors need to replace for new logbooks completed

Works to be completed

Customer actions & recommendations

Equipment required		
Qty	Item	Description
1	EMLED3M	Emergency Light LED BULKHEAD Maintained/Non Maintained 3Hr IP65

Timesheet	Call Date	Travel	Time On Site	Time Off Site	Arrive Back	Total Hours	Engineers Notes
Engineer Andrew Martin	21/09/2020	09:15	09:30	13:00		3.75	

Customer signature

Engineer signature

Customer Position

Engineer Name

Andrew Martin

Reason for no signature if applicable: Not Presen