



# Emergency Light Maintenance Attendance Certificate

System serviced in accordance with BS5266-1

Site name & address    Nuneaton + Bedworth Borough Council Shepperton Court  Coventry Road Nuneaton Post code                    CV11 4NP Contact name                John Sweeney Telephone                    024 7637 6464    Site Mobile Site e-mail Contract number            MD-M58671	Call type                      Routine Maintenance Visit date                    19/10/2020 Job number                    1256594 Appointment booked by    Claire Long System type                    Emergency Lighting Panel type                      none Panel location/number Customer Order Number    Contract extension 4 Engineer                        Andrew Martin
--	---

<b>Site</b>  All relevant information and documentation available <input checked="" type="checkbox"/> Inform customer system on test    NA Check log book for previous faults <input checked="" type="checkbox"/>	<b>Luminaires located at the following positions</b> At each emergency exit door    NA Within 2m of stair treads/level change                                NA Within 2m of exit and safety signs                                        NA At intersection of corridors    NA At each change of direction    NA Outside and within 2m of final exits                                      NA Within 2m of each first aid point                                        NA Within 2m fire fighting equipment and call points                    NA
<b>Luminaires</b>  Main manufacturer/model    8w bulkheads Number of non-maintained luminaires                                      40 Number of non-maintained luminaires, maintained signs Number of maintained luminaires Number of slaves Duration of system tested    3 hour Total number tested    40 No. of luminaires failed	<b>Additional luminaires located at the following positions</b> Lift cars    NA Moving Stairways and walkways    NA Disabled Toilets    NA Motor generator room, control & plant rooms                            NA Covered car parks    NA

<b>System status</b> Have you returned the system to its normal operational state to the best of your knowledge    Yes If not why?
--

<b>Works completed/engineer findings</b>  3 hour emergency light test completed all areas tested no issues logbooks completed
--

<b>Works to be completed</b>
------------------------------

<b>Customer actions &amp; recommendations</b>
---

Timesheet	Call Date	Travel	Time On Site	Time Off Site	Arrive Back	Total Hours	Engineers Notes
Engineer							
Andrew Martin	19/10/2020	08:00	09:15	12:45		4.75	

<b>Customer signature</b>   <b>Customer Position</b> Reason for no signature if applicable:    Not Presen	<b>Engineer signature</b>  <b>Engineer Name</b> Andrew Martin
---	---