

**REPORT OF PERIODIC THOROUGH EXAMINATION
OF HOIST OR LIFT**

as required by the Lifting Operation and Lifting Equipment Regulations 1998;
or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999;
or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: G1B0218596

Plant Code: L27AHH

Previous Report: 010720-002-0003EMO

Site: 00016

Schedule: L0003

Report Number: 030221-002-0004EMO

L0L54

Employer (or owner) of premises	NUNEATON & BEDWORTH BOROUGH COUNCIL	
Address	Catherine Ward Hall, Bedworth, Warwickshire, CV12 8AX	
1. (a) Type of hoist or lift and identification number and description	Passenger/Goods Lift	Hydraulic
(b) Date of construction or reconstruction (if ascertainable)	H+C Dover Elevators Serial No.:- 32841-91 Unknown	
2. (a) Is this the first thorough examination following installation of the equipment at the above site/location?	No	
(b) Were examinations in accordance with an examination scheme?	No	
3. Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use.		
(a) Enclosure of hoistway or liftway.	Yes	
(b) Landing gates and cage gate(s).	Yes	
(c) Interlocks on the landing gates and cage gate(s).	Yes	
(d) Other gate fastenings.	Yes	
(e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.	Yes	
(f) Over-running devices.	Yes	
(g) Suspension ropes or chains, and their attachments.	Not applicable, direct acting cylinder.	
(h) Safety gear, i.e. arrangements for preventing fall of platform or cage.	Yes	
(j) Brakes.	Yes	
(k) Worm or spur gearing.	Not applicable.	
(l) Other electrical equipment.	Yes	
(m) Other parts.	Yes	
4. What parts (if any) were inaccessible?	Enclosed electrical, mechanical and structural components	
5. Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None") :-		
(a) defects found which give rise to imminent danger and require attention immediately.	None	
(b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period.	None	
6. Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.	1000kg/13 persons	
7. Other observations		

This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.


Date of Examination: 02 Feb 2021

Date of Last Examination: 30 Jun 2020

Inspecting Engineer: Mr A Gernon

Date of Next Examination: 02 Aug 2021

Signature:



Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292,
New London House, 6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited
is accredited by the United Kingdom
Accreditation Service



010