

Our Ref.: G1B218596/12/AG4/EMO/RMP

Date: 8th June 2021

**NUNEATON & BEDWORTH BOROUGH COUNCIL**  
**Arthur Alford House**  
**Bedworth**  
**Warwickshire**  
**CV12 0JT**

**For the attention of Arlene Hayden**

Inspection Details

Type : Policy  
Number : G1B218596-12 Report Nos. : 001-001  
Class : Lifting & Handling Plant  
Surveyor : Mr A Gernon  
Date : 7th June 2021  
Location : As attached

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

The attached documentation contains reports on some items of plant and machinery which were not subject to inspection to any particular Regulation. The items concerned are identified and the responsibility for compliance with any regulations deemed applicable by Regulatory Authorities or any other party, in their operation and usage, rests with the owner/user. If you wish any such equipment inspected in accordance with a specific criteria, this must be detailed in the Policy/Contract prior to the inspection taking place.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the inspection methods and procedures as documented in Section 7.1 of the Company Quality Assurance Policy (Manual).

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.

# PLANT INSPECTION REPORT

**Policy:** G1B0218596

**Previous Report:** 230620-001-0002EMO

**Site :** 00012

**Report Number :** 080621-001-0003EMO

**PIR1**

**Occupier** NUNEATON & BEDWORTH BOROUGH COUNCIL

**Address** Arthur Alford House, Bedworth,  
Warwickshire, CV12 0JT

Sched No.	Plant Code	Item	Remarks
L0001	L30A10	Stair Lift S.No.:MO2132388 SWL: 115 kg/1 Person Locn.:On Site	Remote control not working advise attention.

**This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).**


**Date of Inspection:** 07 Jun 2021

**Date of Last Inspection:** 22 Jun 2020

**Inspecting Engineer:** Mr A Gernon

**Date of Next Inspection:** 07 Jun 2022

**Signature:**



**Qualification:** Engineer Surveyor

**HSB Engineering Insurance Services Limited**

Registered in England and Wales: 03010292,  
New London House, 6 London Street, London EC3R 7LP  
Registered as a branch in Ireland: 906105  
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited  
is accredited by the United Kingdom  
Accreditation Service

