

Our Ref.: G1B218596/46/AG4/EMO/RMP

Date: 8th June 2021

NUNEATON & BEDWORTH BOROUGH COUNCIL
Town Hall
Coton Road
Nuneaton
Warwickshire
CV11 5AA

For the attention of Bev Soanes

Inspection Details

Type : Policy
Number : G1B218596-46 Report Nos. : 001-001
Class : Lifting & Handling Plant
Surveyor : Mr A Gernon
Date : 7th June 2021
Location : As attached

Dear Sirs

Our Engineer Surveyor attended as above in order to carry out the examination detailed.

Observations and comments made in our reports are for your own consideration as to the extent of repair or other maintenance work which you intend to undertake. The company has no liability for instructions to undertake work on any item other than those which require action to prevent imminent danger.

The attached documentation contains reports on some items of plant and machinery which were not subject to inspection to any particular Regulation. The items concerned are identified and the responsibility for compliance with any regulations deemed applicable by Regulatory Authorities or any other party, in their operation and usage, rests with the owner/user. If you wish any such equipment inspected in accordance with a specific criteria, this must be detailed in the Policy/Contract prior to the inspection taking place.

In accordance with our accreditation procedures, you may reproduce the attached report in whole, or in part for use by yourselves or a third party. The examination methods and procedures used to comply with the detailed particular Statutory Regulations, which are applicable to the Plant, are stated in the inspection methods and procedures as documented in Section 7.1 of the Company Quality Assurance Policy (Manual).

We trust that you continue to find our services to your satisfaction.

Yours faithfully

HSB Customer Solutions Centre.

PLANT INSPECTION REPORT



Policy: G1B0218596

Previous Report: 250620-001-0002EMO

Site : 00046

Report Number : 080621-001-0003EMO

PIR1

Occupier NUNEATON & BEDWORTH BOROUGH COUNCIL

Address Shepperton Court, Coventry Road,
Nuneaton, Warwickshire
CV11 4NP

Sched No.	Plant Code	Item	Remarks
L0001	L30A10	Stair Lift S.No.:U26014464307 SWL: 135 kg Locn.:On Site	Advise service log card is kept on site. Year of manufacture: 2014

This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).

Date of Inspection: 07 Jun 2021

Date of Last Inspection: 22 Jun 2020

Inspecting Engineer: Mr A Gernon

Date of Next Inspection: 07 Jun 2022

Signature:

Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited

Registered in England and Wales: 03010292,
New London House, 6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited
is accredited by the United Kingdom
Accreditation Service

