



Emergency Light Maintenance Attendance Certificate

System serviced in accordance with BS5266-1

Site name & address Nuneaton + Bedworth Borough Council Poets Corner 20 Drayton Road, Burns Walk, Milton Close Bedworth Post code CV12 9EY Contact name John Sweeney Telephone 024 7637 6464 Site Mobile Site e-mail trinityrecords@nuneatonandbedworth.gov.uk Contract number MD-M58685	Call type Routine Maintenance Visit date 12/07/2021 Job number -1363887 Appointment booked by Kate Gee System type Emergency Lighting CORE Panel type notifier id2000 Panel location/number Customer Order Number ES000767 Engineer Andrew Martin
---	---

Site	Luminaires located at the following positions
All relevant information and documentation available <input type="checkbox"/> Inform customer system on test <input type="checkbox"/> Check log book for previous faults <input type="checkbox"/>	At each emergency exit door NA Within 2m of stair treads/level change NA Within 2m of exit and safety signs NA At intersection of corridors NA At each change of direction NA Outside and within 2m of final exits NA Within 2m of each first aid point NA Within 2m fire fighting equipment and call points NA
Luminaires	Additional luminaires located at the following positions
Main manufacturer/model spotlights Number of non-maintained luminaires 12 Number of non-maintained luminaires, maintained signs Number of maintained luminaires Number of slaves Duration of system tested 3 hour Total number tested 12 No. of luminaires failed	Lift cars NA Moving Stairways and walkways NA Disabled Toilets NA Motor generator room, control & plant rooms NA Covered car parks NA

System status
Have you returned the system to its normal operational state to the best of your knowledge Yes If not why?

Works completed/engineer findings
3 hour emergency light test completed all areas tested no issues logbooks completed

Works to be completed

Customer actions & recommendations

Timesheet							
Engineer	Call Date	Travel	Time On Site	Time Off Site	Arrive Back	Total Hours	Engineers Notes
Andrew Martin	12/07/2021	14:10	14:10	17:30	18:45	4.58	

Customer signature	Engineer signature
Customer Position	Engineer Name Andrew Martin
Reason for no signature if applicable: Not Presen	