



Emergency Light Maintenance Attendance Certificate

System serviced in accordance with BS5266-1

Site name & address Nuneaton + Bedworth Borough Council Springdale Court Attleborough Road Nuneaton Post code CV11 4TU Contact name John Sweeney Telephone 024 7637 6464 Site Mobile Site e-mail trinityrecords@nuneatonandbedworth.gov.uk Contract number MD-M58672	Call type Routine Maintenance Visit date 07/07/2021 Job number -1363854 Appointment booked by Luke Black System type Emergency Lighting CORE Panel type emergency lighting Panel location/number Customer Order Number ES000767 Engineer Andrew Martin
---	---

Site	Luminaires located at the following positions
All relevant information and documentation available p Inform customer system on test NA Check log book for previous faults p	At each emergency exit door NA Within 2m of stair treads/level change NA Within 2m of exit and safety signs NA At intersection of corridors NA At each change of direction NA Outside and within 2m of final exits NA Within 2m of each first aid point NA Within 2m fire fighting equipment and call points NA
Luminaires	Additional luminaires located at the following positions
Main manufacturer/model spots and 8w bulkheads Number of non-maintained luminaires 44 Number of non-maintained luminaires, maintained signs Number of maintained luminaires Number of slaves Duration of system tested 3 hour Total number tested 44 No. of luminaires failed 2	Lift cars NA Moving Stairways and walkways NA Disabled Toilets NA Motor generator room, control & plant rooms NA Covered car parks NA

System status
Have you returned the system to its normal operational state to the best of your knowledge Yes If not why?

Works completed/engineer findings
3 hour emergency light test completed all areas tested no issues 2 x spots failed ground floor adj flat 16 and adj flat 14 need replacing for new logbooks completed


Works to be completed

Customer actions & recommendations

Timesheet																
<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Engineer</th> <th style="width: 15%;">Call Date</th> <th style="width: 10%;">Travel</th> <th style="width: 10%;">Time On Site</th> <th style="width: 10%;">Time Off Site</th> <th style="width: 10%;">Arrive Back</th> <th style="width: 10%;">Total Hours</th> <th style="width: 20%;">Engineers Notes</th> </tr> </thead> <tbody> <tr> <td>Andrew Martin</td> <td>07/07/2021</td> <td>07:30</td> <td>09:00</td> <td>12:40</td> <td></td> <td>5.17</td> <td></td> </tr> </tbody> </table>	Engineer	Call Date	Travel	Time On Site	Time Off Site	Arrive Back	Total Hours	Engineers Notes	Andrew Martin	07/07/2021	07:30	09:00	12:40		5.17	
Engineer	Call Date	Travel	Time On Site	Time Off Site	Arrive Back	Total Hours	Engineers Notes									
Andrew Martin	07/07/2021	07:30	09:00	12:40		5.17										

Customer signature

Engineer signature



Customer Position

Engineer Name

Andrew Martin

Reason for no signature if applicable: Not Presen