



Emergency Light Maintenance Attendance Certificate

System serviced in accordance with BS5266-1

Site name & address	Nuneaton + Bedworth Borough Council The Grove Complex Off The Grove Chapel Street Bedworth	Call type	Routine Maintenance
Post code	CV12 8JL	Visit date	23/07/2021
Contact name	John Sweeney	Job number	-1363866
Telephone	024 7637 6464 Site Mobile 07748982740	Appointment booked by	Kate Gee
Site e-mail	trinityrecords@nuneatonandbedworth.gov.uk	System type	Emergency Lighting CORE
Contract number	MD-M58691	Panel type	none
		Panel location/number	
		Customer Order Number	ES000767
		Engineer	Andrew Martin

Site	Luminaires located at the following positions
All relevant information and documentation available	At each emergency exit door NA
Inform customer system on test	Within 2m of stair treads/level change NA
Check log book for previous faults	Within 2m of exit and safety signs NA
	At intersection of corridors NA
	At each change of direction NA
	Outside and within 2m of final exits NA
	Within 2m of each first aid point NA
	Within 2m fire fighting equipment and call points NA
Luminaires	Additional luminaires located at the following positions
Main manufacturer/model	Lift cars NA
8w bulkheads	Moving Stairways and walkways NA
Number of non-maintained luminaires	Disabled Toilets NA
50	Motor generator room, control & plant rooms NA
Number of non-maintained luminaires, maintained signs	Covered car parks NA
Number of maintained luminaires	
Number of slaves	
Duration of system tested	
3 hour	
Total number tested	
50	
No. of luminaires failed	
3	

System status
Have you returned the system to its normal operational state to the best of your knowledge Yes
If not why?

Works completed/engineer findings
3 hour emergency light test completed all areas tested 3 x emls failed adj managers office,adj ground floor refuse and adj flat 69 need to be replaced for new logbooks completed

Works to be completed

Customer actions & recommendations

Equipment required		
Qty	Item	Description
3	ZZZZ	Non Listed Part - Please Update Description recessed 8w bulkheads

Timesheet							
Engineer	Call Date	Travel	Time On Site	Time Off Site	Arrive Back	Total Hours	Engineers Notes
Andrew Martin	23/07/2021	12:15	12:15	16:00	17:45	5.5	

Customer signature

Engineer signature



Customer Position

Engineer Name

Andrew Martin

Reason for no signature if applicable: Not Presen