

Name of facility	Bedworth Leisure Centre
Address	CV12 8NN

QUALITY RATING

General Condition	Excellent		Good	x	Average		Poor		Very Poor	
--------------------------	-----------	--	------	---	---------	--	------	--	-----------	--

Need for capital investment	Minimal		Moderate		Significant	x				
------------------------------------	---------	--	----------	--	-------------	---	--	--	--	--

Facility Quality

<i>Swimming Pool 25m x 6 lanes + Learner pool</i>	Excellent		Good	x	Average		Poor		Very Poor	
---	-----------	--	------	---	---------	--	------	--	-----------	--

<i>Reception</i>	Excellent		Good	x	Average		Poor		Very Poor	
------------------	-----------	--	------	---	---------	--	------	--	-----------	--

<i>Pool Changing</i>	Excellent		Good		Average	x	Poor		Very Poor	
----------------------	-----------	--	------	--	---------	---	------	--	-----------	--

<i>Dryside Changing</i>	Excellent		Good	x	Average		Poor		Very Poor	
-------------------------	-----------	--	------	---	---------	--	------	--	-----------	--

<i>Fitness Suite + studio</i>	Excellent		Good	x	Average		Poor		Very Poor	
-------------------------------	-----------	--	------	---	---------	--	------	--	-----------	--

NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED										5
---	--	--	--	--	--	--	--	--	--	---

Disability Access	Full	x	Partial		No					
--------------------------	------	---	---------	--	----	--	--	--	--	--

Served by Public Transport	Yes	x	No							
-----------------------------------	-----	---	----	--	--	--	--	--	--	--

Good Natural Presence	Excellent		Good	x	Average		Poor			
------------------------------	-----------	--	------	---	---------	--	------	--	--	--

Well Signposted	Good	x	Some		Poor					
------------------------	------	---	------	--	------	--	--	--	--	--

Car Parking	Good	x	Some		Poor					
--------------------	------	---	------	--	------	--	--	--	--	--

Development Potential	Lots	x	Some		No potential					
------------------------------	------	---	------	--	--------------	--	--	--	--	--

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

76%

Name of facility	Jubilee Sports Centre
Address	CV10 7EZ

QUALITY RATING

General Condition	Excellent		Good	x	Average		Poor		Very Poor	
Need for capital investment	Minimal		Moderate		Significant	x				

Facility Quality										
<i>4 court sports hall</i>	Excellent		Good	x	Average		Poor		Very Poor	
<i>Reception</i>	Excellent		Good	x	Average		Poor		Very Poor	
<i>3G rubber crumb 5 --a-side</i>	Excellent	x	Good		Average		Poor		Very Poor	
<i>Dryside Changing</i>	Excellent		Good		Average	x	Poor		Very Poor	
<i>Squash courts</i>	Excellent		Good		Average	x	Poor		Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED										5

Disability Access	Full		Partial	x	No			
Served by Public Transport	Yes	x	No					
Good Natural Presence	Excellent		Good	x	Average		Poor	
Well Signposted	Good	x	Some		Poor			
Car Parking	Good	x	Some		Poor			
Development Potential	Lots	x	Some		No potential			

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

72%

Name of facility	Nuneaton Academy
Address	CV10 7PD

QUALITY RATING

General Condition	Excellent	x	Good		Average		Poor		Very Poor	
Need for capital investment	Minimal	x	Moderate		Significant					

Facility Quality										
<i>4 court sports hall</i>	Excellent		Good	x	Average		Poor		Very Poor	
<i>Reception</i>	Excellent	x	Good		Average		Poor		Very Poor	
<i>3G rubber crumb 5 --a-side</i>	Excellent	x	Good		Average		Poor		Very Poor	
<i>Dryside Changing</i>	Excellent		Good	x	Average		Poor		Very Poor	
<i>Fitness Suite & Studio</i>	Excellent		Good	x	Average		Poor		Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED										5

Disability Access	Full	x	Partial		No					
Served by Public Transport	Yes		No	x						
Good Natural Presence	Excellent		Good		Average	x	Poor			
Well Signposted	Good	x	Some		Poor					
Car Parking	Good	x	Some		Poor					
Development Potential	Lots		Some	x	No potential					

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

81%

Name of facility	Etone Sports Centre
Address	CV11 6AA

QUALITY RATING

General Condition	Excellent		Good		Average	x	Poor		Very Poor	
Need for capital investment	Minimal		Moderate		Significant	x				

Facility Quality										
4 court sports hall	Excellent		Good	x	Average		Poor		Very Poor	
Reception	Excellent		Good		Average	x	Poor		Very Poor	
AGP	Excellent		Good		Average	x	Poor		Very Poor	
Dryside Changing	Excellent		Good		Average	x	Poor		Very Poor	
Squash courts	Excellent		Good		Average	x	Poor		Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED										5

Disability Access	Full		Partial	x	No			
Served by Public Transport	Yes	x	No					
Good Natural Presence	Excellent		Good	x	Average		Poor	
Well Signposted	Good	x	Some		Poor			
Car Parking	Good	x	Some		Poor			
Development Potential	Lots	x	Some		No potential			

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

63%

Name of facility	Pingles Leisure Centre
Address	CV11 4LX

QUALITY RATING

General Condition	Excellent	x	Good		Average		Poor		Very Poor	
Need for capital investment	Minimal	x	Moderate		Significant					

Facility Quality										
<i>Swimming Pool 25 x 8 lanes</i>	Excellent	x	Good		Average		Poor		Very Poor	
<i>Reception</i>	Excellent		Good	x	Average		Poor		Very Poor	
<i>Village Changing</i>	Excellent		Good	x	Average		Poor		Very Poor	
<i>Dryside Changing</i>	Excellent	x	Good		Average		Poor		Very Poor	
<i>Freeform learner and outdoor pool</i>	Excellent		Good	x	Average		Poor		Very Poor	
<i>Fitness Suite + Studio</i>	Excellent	x	Good		Average		Poor		Very Poor	
<i>Café</i>	Excellent	x	Good		Average		Poor		Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED										7

Disability Access	Full	x	Partial		No			
Served by Public Transport	Yes	x	No					
Good Natural Presence	Excellent	x	Good		Average		Poor	
Well Signposted	Good	x	Some		Poor			
Car Parking	Good	x	Some		Poor			
Development Potential	Lots		Some	x	No potential			

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

93%